

Monitoring Memo

15May2025

Temporary change in TVP battery box	
From:	Jason Daoust
Re:	TVP Battery Box


Dear Ellab Team,

Due to long lead times in the current battery box, we have made the decision to temporarily substitute the battery box on the TrackView Pro transmitters. The substitute will be almost visually identical but will have different springs with a higher strength rating. This means the batteries will be held in tighter and may require the use of a screwdriver to release the batteries from the holders. This substitution will only be until the originally specified battery box becomes available again, which may be in a few months.

Caution: If using a tool to remove the battery, please exercise care to avoid damaging the batteries, the battery box terminals, or the device itself.

Any questions, please contact support@ellab.com

Original version on left, temporary version on right.



May require screwdriver to remove the batteries.



Yours sincerely,

Jason Daoust
 Director of Monitoring Solutions